




Case Study- Improving Reliability of Descale Pumps





Our latest article in [World Pumps](#) Magazine discusses a case where advanced technology, targeted upgrades, and thinking outside the box helped a steel mill avoid costly downtime.



When facing repeated failures of their descale pumps, Hydro helped the mill salvage enough usable components from the failed pieces of equipment to return a fully functional, upgraded piece of equipment to service. By performing an in-depth root cause analysis and implementing material and design upgrades, the equipment has been transformed from a bad actor to a reliable piece of equipment.

Read the [full case study here](#).